



Software Update Notification

PSS0023-07: Malvern Link v1.39 software



Abstract

This document details the release of software PSS0023-07. This is version 1.39 of the automation software for the Insitec laser diffraction system. It covers software issues that have been fixed and new features introduced. This information is required to perform a risk analysis to determine if the software should be installed. In this risk analysis the benefits of the new features provided and resolved software issues must be weighed against the risk of new issues that may be introduced to vital areas of the software or possible changes to the results of future analysis. Installation instructions are provided.

Installation

It is assumed that you have authority to install or update software within your facility. It is also assumed that you have Administrator rights for the system upon which the software is installed, as this is a requirement of the installation process. If you do not have this authority please consult with your I.T. support department before proceeding.

Minimum System Requirements

The key minimum requirements for running this software are highlighted in the table below:

Feature	Specification
CPU	Pentium IV 2 GHz or Pentium M 1.4 GHz
Memory	1GB or 2GB when using Windows Vista.
Hard Disk Storage	80Gbyte
Additional Storage Media	CD-ROM drive
Display Resolution	1024 x 768
Connectivity	2 RS232 COM port
Operating System	Windows Vista Business or Enterprise Edition [™] Windows XP Professional [™] with SP2 or higher installed Windows 2000 Professional [™] with SP4 or higher installed

Although the software has been tested using Windows 2000TM and Windows Vista Business Edition TM, Windows XP Professional TM is the preferred operating system.







Instrument compatibility

The Malvern Link v1.38 software is compatible with the following model of Insitec

ITB5xxx and ITT5xxx : Insitec 2000 model

IDC5xxx : Insitec 2004 modelITX5xxx : Insitec X modelILC5xxx : Insitec Liquid

ITB	ITT	ITX	IDC	ILC
ITB5121	ITT5121	ITX5121	IDC5111	ILC5112
ITB5122	ITT5123	ITX5123	IDC5113	ILC5212
ITB5123	ITT5221	ITX5131	IDC5121	ILC5312
ITB5221	ITT5223	ITX5133	IDC5123	ILC5412
ITB5222	ITT5321	ITX5221	IDC5131	ILC5612
ITB5321	ITT5323	ITX5223	IDC5133	
ITB5322	ITT5321	ITX5231	IDC5141	
ITB5421	ITT5323	ITX5233	IDC5143	
ITB5422		ITX5321	IDC5211	
		ITX5323	IDC5213	
		ITX5331	IDC5221	
		ITX5333	IDC5223	
		ITX5421	IDC5231	
		ITX5423	IDC5233	
		ITX5431	IDC5241	
		ITX5433	IDC5243	
			IDC5311	
			IDC5313	
			IDC5321	
			IDC5323	
			IDC5331	
			IDC5333	
			IDC5341	
			IDC5343	
			IDC5411	
			IDC5413	
			IDC5421	
			IDC5423	
			IDC5431	
			IDC5433	
			IDC5441	
			IDC5443	

Note: Malvern Link version 1.36 onwards is not compatible with Insitec 97 models.







Installation Instructions

Before installing Malvern Link the following software must be installed:

Software		Description	
1	Hasp USB key driver	iFix $^{\text{IM}}$ hardware key driver. The driver is part of CD-ROM in the following folder :	
		\Tools\iFix Usb key Driver	
2	iFix [™] Software version 3.5	GE Fanuc Scada [™] package	
3	RTSizer Software (version 7.11 minimum)	Insitec Software	

The Malvern Link software is provided on one auto-loading CD-ROM. Inserting the CD-ROM into a system configured to auto-run a CD will run the installation program automatically. If your system does not support this feature run the **\setup.exe** program from the root directory of your CD drive.

Note: The full installation procedure is described in the following document

\Technical Doc\ TNML-General Setup Instructions (GM - 20APR2005).pdf.

Uninstall Procedure

The Malvern Link software can be uninstalled using the standard **Add/Remove Programs** feature in the Windows 'Control panel'.







New Features

Windows Vista™ Support

Note:

In order to be vista compatible you must turn off the Windows U.A.C feature. This is because iFix and RTSizer are not fully compatible with the new Windows directory structure and the new Windows registry database requirement.

Fixed Issues

The following Software Change Requests (SCRs) have been implemented in version 1.38 of the Malvern Link software:

SCR Number	Description	Comments	
7986	PC hangs up after a background measurement		
7987	Wiper error appears after opening the iFix Tag windows	Fixed	
7988	Fast cleaning option	Implemented	
7989	Add a timer on low scattering signal error before stopping At-Line Measurement	Implemented	
8049	Problem with customer specific configuration.	Fixed	
8055	Add an option for clearing the alarms automatically	Implemented	
8056	The batch tracker should report an error if the batch is empty (no record)	Implemented	
8448	The Batch Results window doesn't display long PCV title	Fixed	
8449	Malvern Link should not return "Undefined Error". It should be more explicit	Implemented	

Deletions

From version 1.36, Malvern Link software doesn't support Insitec 97 models

Known Issues

If you find an issue with this software which is not listed below, please report it to Malvern instruments via your local representative or directly to the UK helpdesk.








New features

Fast Cleaning Option

An option has been added in order to add a cycle on each valve.


The user decides when the cycle has to be active. The configuration parameters are available in the valve configuration window.

When the option is activated on the Inlet valve, the booster cleans the probe regularly.













RTSizer Error. Timeout before starting the action on alarm

After a measurement error, the action on is automatically started. The new option defines a buffer time before starting the action.











Process Control Variables error

If a background is requested during a scheduler, a new option has been added to stop the scheduler first before performing the background










Automatic Clear Alarms option

The new options allows emptying the alarm list when there is no alarm active











New batch tracker error

A new error has been added. The error is raised when the number of record in the batch results is below a threshold. The user has to define the threshold. If the value is 0 the error will never be seen.










At-Line Vibration Feeder Adjustment

A new tag has been added to the At-Line option. The tag allows vibration feeder adjustment.

Clicking on the button Start/Stop vibration on the mimic will set the vibration to 0 for stopping or set the vibration to the previous value for starting the vibration



Software Update History

The software update notification documents relating to previous versions of the Malvern Link software are available from the support section of the Malvern Instruments website (www.malvern.com). Please refer to these documents for details of the new features released within each version of the Malvern Link software.

